

D-Link DWA-111 Wireless G USB Adapter Release Note

Utility: V1.21b04

Driver:

Vista UI Version : v1.21b04 (Use kernal version:v2.1.14.120)

Vista Driver version : v3.1.5.0(WHQL)

Vista WlanDll version : v1.30.120.60

Vista WlanWps version: v1.4.112.6070

2KXP UI Version : v1.21b04 (Use kernal version:v1.4.22.336)

2KXP Driver version : v1.3.2.0(WHQL)

2KXP WlanDll version : v336.70.1.10

Hardware: A1

Date: 2009/03/10

Problems Resolved:

Fix WPS sometimes cannot get IP when first run on 2KXP

Utility: V1.21b03

Driver:

Vista UI Version : v1.20b03 (Use kernal version:v2.1.4.118)

Vista Driver version : v3.0.3.0

Vista WlanDll version : v1.28.118.60

2KXP UI Version : v1.20b03 (Use kernal version:v1.4.10.334)

2KXP Driver version : v1.1.3.0

2KXP WlanDll version : v334.70.1.9

Hardware: A1

Date: 2008/07/01

Problems Resolved:

1)<Utility>Add languages Croatian, Romanian and Slovenian wizard WZC page translation.

2)<Utility>Fixed 2KXP link rate sometimes is only 1Mbps issue.

Utility: V1.10b05

Driver:

2K/XP Driver: v1.1.3.0

Vista Driver: v3.0.3.0

Hardware: A1

Date: 2007/06/01

Problems Resolved:

(1) Pass Vista WHQL certificate logo.

Enhancements:

Support 15 multi-language.

Support Vista

Utility: V1.10b03

Driver:

Vista UI Version : v1.20b03 (Use kernal version:v2.1.4.118)

Vista Driver version : v3.0.3.0

Vista WlanDll version : v1.28.118.60

2KXP UI Version : v1.20b03 (Use kernal version:v1.4.10.334)

2KXP Driver version : v1.1.3.0

2KXP WlanDll version : v334.70.1.9

Hardware: **A1**

1st release